



Pump Assembly Rebuild — Sample Report

Work order	WO-4471
Client	Acme Manufacturing
Date	21 Sep 2026
Prepared by	J. Alvarez



PN-4471
Bearing housing, rear axle
IMG_0231.jpg



PN-4472
Coupling flange, worn edge
IMG_0233.jpg




PN-4475
Seal replacement, front
IMG_0238.jpg



PN-4480
Final assembly, torque-checked
IMG_0241.jpg

Reweld before ship
— flagged during inspection



SAMPLE PHOTO

PN-4490
Weld seam, requires rework — see annotation
IMG_0247.jpg